





\*Please maintain not to exceed speed limit. Excess speed will dramatically reduce bearing life.



\*Please refer to the concerned product introduction page about the details.



\*Please maintain not to exceed speed limit. Excess speed will dramatically reduce bearing life.  
 \*1 : Maximum rotating speed at the cutting tool. \*2 : Maximum allowable motor speed for the spindle.



\*Please refer to the concerned product introduction page about the details.